



# CNC TABLE

Outer Frame must be absolutely square and perfectly flat on the top surface.  
 Legs must be exactly the same length and perpendicular to the ground and top frame.