

Control

	Z+	AXIS	POSITION	Absolute	Offset	State	100ipal
		X	-0.35mm	0.838mm	1.188mm	HOMED	OK
X+	Z0		96.502mm	96.692mm	0.19mm	HOMED	OK

ERROR: X axis position -0.162mm is less than minimum sof...



Clear

Level

Message

X axis position -0.162mm is less than minimum soft limit 0mm
While executing GCode block:G0 X-1 Y0 Z0 A0

At: <MDI>:2

Caused by: X axis position -0.162mm is less than minimum soft limit 0mm